Golden Gate Theater Reuse











Current exterior views of Golden Gate Theater (clockwise from top left): View southwest of north façade (right) and east elevation (left); View southeast of north façade; Detail view of north façade; View east of west elevation; View southwest of north façade (right) and east elevation (left)

Golden Gate Theater Reuse











Historic exterior views of Golden Gate Theater (clockwise from top left): View southwest showing Vega Building (demolished) (date unknown, Los Angeles Public Library); View southwest showing Vega Building (date unknown, California State Library); View of entrance to courtyard from Vega Building (c. 1980s, Tom Zimmerman Photography); View of north façade entry detail (c. 1980s, Tom Zimmerman Photography); Aerial view showing Vega Building (1935, Spence Air Photo Archives, UCLA)

Golden Gate Theater Reuse Lobby







View southeast View southwest View west






View southeast View northeast

Golden Gate Theater Reuse Auditorium







View southwest

View southwest

View east





View north View northeast

Golden Gate Theater Reuse Stage and Proscenium Arch




Historic photo, view southeast (Los Angeles Public Library photo no. 0015324, date unknown)




Existing, view southeast

Golden Gate Theater Reuse




Extant ceiling-mounted lighting fixtures at balcony underside (left) and extant ceiling-mounted lighting fixtures above balcony (right)


Site plan




Retaining wall detail




North and east elevations







South and west elevations




North elevation




Ground floor plan




Mezzanine level plan




Interior section




Interior section




Interior section




Lower level reflected ceiling plan



Upper level reflected ceiling plan




Previously approved signage








Previously approved signage



Previously approved signage



Compliance with Mitigation Measures

- Use of CHBC
- Attachments for banner signage
- Feasibility of heating and cooling
- •Treatment of high volume auditorium space
- •Treatment of new wall for stage fly tower mezzanine
- Treatment of coffered balcony underside
- Options for east elevation fire escape stair
- Selection of exterior paint colors
- HABS photography
- Lobby stair documentation

